


JOINT STOCK COMPANY „SIPMA“ S.A.
20-469 LUBLIN, Budowlana Street 8
phone 450-71, tlx 0642732, fax 447-93

**MANUAL
INSTRUCTION
and
SPARE PARTS
CATALOGUE
of
GRAIN CRUSCHER
H-730, H-730/2
H-733, H-733/1**

Sipma®



Valse H730

1	8730010000		1
2	8730020000	Ben for valse	1
3	8730030000		1
4	87300400000	Valse	1
5	87300500000	Træk valse	1
6	87300600000	Remskive	1
7	8730070000		1
8	SF112M-4TR1	El-motor	1
9	87300001000	Strammebolt	2
9a	87300004000	Strammebolt	2
10	873300052000	Strammehåndtag	2
11	87300003000	Plade for motor	1
12	873300054000	Strammebolt	1
13	87300300002	Plade	2
14	10 mm	Møtrik	1
15	8730005000		1
16	87300000004	Lejehus	4
17	87300000005	Lejedæksel	4
18	87300000006	Skive	2
19	8730000070	Remskive	1
20	8730000080		1
21	8730010080	Holder d. magnet	1
22	87300000011	Tandhjul	2
23	8730000120		1
24	8730000130	Kabelholder	1
25	87300106000	Lukkeplade	1
26	35 x 45 x 1	Shims	3
27	87300100008	Forbindelsesstang f. skod	1
28	PNM86488-40	Filtring	4
29	87300107000	Lukkelse	1
30	87300100010	Styreskinde	1
31	12 mm	Fjederskive	2
32	87300300011	Skrabeplade	2
33	8730006000		1
41	6 mm	Skive	15
42	10 mm	Skive	8
43	12 mm	Skive	14
44	17 mm	Skive	2
45	6 mm	Skive	5
46	6 mm	Fjederskive	15

Valse H730

47	8 mm	Skive	3
48	10 mm	Skive	9
49	12 mm	Skive	12
50	8 x55	Bolt	8
51	12 x 55	Bolt	8
52	6 x 16	Bolt	12
53	8 x 30	Bolt	3
54	10 x 40	Bolt	4
55	Inge position		
56	12 x 35	Bolt	4
57	6 x 16	Bolt	2
58	12 x 35	Bolt	2
59	Ingen position		
60	85044-8x7x28	Pasfeder	2
61	85044-10x8x63	Pasfeder	1
62	10 mm 90 gr.	Smørenippel	3
63	10 mm 45 gr.	Smørenippel	1
64	Fag1208	Leje	4
* 65	PNM86488-40	Filtring 40x52x5	2
66	5M	Møtrik	6
67	6M	Møtrik	2
68	8M	Møtrik	8
69	10M	Møtrik	6
70	12M	Møtrik	8
71	12 M	Låsemøtrik	6
72	HC1500	Rem	1
73	8 mm	Skive	8
80	10x30	Bolt	5
81	100x50x18	Magnet	2
83	6 M	Møtrik	2
84	8 x 18	Pindbolt	1
85	8 mm	Skive	3
86	2 mm	Splitte	3
87	6x20	Bolt	1
88	6x16	Bolt	2
89	6 mm	Låsemøtrik	1

* 1- 8733000120